

Linksys LLC

131 Theory Drive, Irvine, CA 92617, USA

Tel: 949-842-0744 / Fax: 949-823-3002

Class II Change Letter

Date: 2014/6/3

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046
U.S.A.

To whom it may concern,

Request for Class II Permissive Change

FCC ID: Q87-RE6500 / Grant Date: 04/24/2014

Pursuant to CFR 2.1043, Linksys LLC hereby requests a Class II Permissive Change.

The model name shall be same as before.

Modification:

This product is an extension of original report under Sporton project number: 421849

1. Adding 4 higher gain antennas. The more detail information as following table.

Ant.	Brand	Model Name	Antenna Type	Connector	Gain (dBi)		Cable Loss (dB)		True Gain (dBi)	
					2.4GHz	5GHz	2.4GHz	5GHz	2.4GHz	5GHz
1	Joymax	TWX-1561RSXX-711	Dipole	Reversed-SMA	5.5	5.62	1.0	2.8	4.50	2.82
2	Joymax	TWX-1561RSXX-711	Dipole	Reversed-SMA	5.5	5.62	2.8	1.0	2.70	4.62
3	Cortec	AN2450-9220BRS	Dipole	SMA Male Reverse	5.03	5.01	1.0	2.8	4.03	2.21
4	Cortec	AN2450-9220BRS	Dipole	SMA Male Reverse	5.03	5.01	2.8	1.0	2.23	4.01

2. Changing 5GHz Band 1 to "New rule" from "Old rule".

Sincerely,

Applicant's company name : Linksys LLC

Applicant's company address : 131 Theory Drive, Irvine, CA 92617, USA

Signature : *DarrellTennis*

Name and Job Title : Darrell Tennis / Senior Manager, Regulatory Compliance

E-Mail : Darrell.Tennis@belkin.com

Tel. : 949-842-0744