



Cisco-Linksys LLC

121 Theory Drive Irvine, CA 92617 (USA)

Phone: 949-261-1288 Fax: 949-823-3002

Date: July 8, 2008

To whom it may concern

It is acknowledged by Cisco-Linksys LLC.. that the modification list below will be installed to our Model: WAP4410N in order to comply with FCC/ CE Approval requirements. These modifications will be incorporated into each unit sold and mass production under the rules.

Change transformer to 0811A HN2404SG at T1

Yours sincerely,

A handwritten signature in blue ink, appearing to read "DT".

Darrell Tennis/ Manager, Regulatory Compliance
Cisco-Linksys LLC
TEL: +1 949-910-7048
FAX: +1-949-823-3002
E-Mail: dtennis@cisco.com