



47173 Benicia Street, Fremont CA 94538
Tel: 510-771-1000, Fax: 510-661-0888

Federal Communication Commissions
7435 Oakland Mills Road
Columbia MD 21046

Subject: Request FCC to replace previous submitted DTS test report

Ref: Applicant: Cisco-Linksys LLC
FCC ID: Q87-WM821M
TCB Assessment no: AN07T7308
Grant date: 11/05/2007

To Whom It May Concern:

CCS-TCB received a written request from the agent, Compliance Certification Services, Inc. of Cisco-Linksys LLC for requesting to superseding the DTS test report. Due to some typos as specified in another request letter submitted by the agent, the Grantee and agent are requesting FCC to delete the following files from database:

Test Report 1	Test Report	11/05/2007	pdf	11/05/2007
Test Report 2	Test Report	11/05/2007	pdf	11/05/2007

The correct test reports have been uploaded to FCC with description of "Revised DTS test report I" and "Revised DTS test report II"

Best Regards

A handwritten signature in black ink, appearing to read "Mike Kuo 11/19".

Mike Kuo / V.P.
Compliance Certification Services
Nov. 19, 2007