




Analyzer Settings

HP8595EM

CF: 5300.00 MHz
SPAN: 20.00 MHz
RB 3.000 MHz
VB 3.000 MHz
Detector POS
Att 10
RL Offset 0.00
Sweep Time 40.0s
Ref Lvl: -38.00DBM

Comments

5300 MHz
30 minute observation
Non-Occupancy Period
after radar detected
(Bin1)

Cursor 1 5297.75(-56.62

0.000 0.00

