

PHOTOS TEST REPORT

FROM



Test of: Aruba Networks, Inc
to

To: FCC CFR 47 Part 15 Subpart E 15.407

Test Report Serial No.: ARUB206 – 214 215

This report supersedes: NONE

Applicant: Aruba Networks, Inc
1344 Crossman Ave.
Sunnyvale, 94089
USA

Issue Date: 08 January 2016

This Test Report is Issued Under the Authority of:

MiCOM Labs, Inc.
575 Boulder Court
Pleasanton California 94566
USA
Phone: +1 (925) 462-0304
Fax: +1 (925) 462-0306
www.micomlabs.com




MiCOM Labs is an ISO 17025 Accredited Testing Laboratory

1. Test Setup Photographs


1.1.1. Test Setup - RE#1 - Radiated Emissions - 3m Chamber

AP214 TX Spur ant-13b




This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP214 TX Spur ant-18




This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP214 TX Spur ant-19




This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP214 TX Spur ant-1B




This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP214 TX Spur ant-20w




This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP215 TX Spur



This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

1.1.2. Test Setup - RF#2 – Conducted



This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

RF Conducted



This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com