

Report No.: 0312720
Model No.: 3215

Pursuant to FCC Part 15 Section 15. 735 Emissions Requirement


PLT: 18.88ms

-0.04dB

FB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: LT
(Kenny Wong)

Date: 7/8/03

Checked By: [Signature]
(Anthony Chan)

Date: 8/8/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 80ms

F: 49.860900MHz

Report No.: 0312720
Model No.: 3215

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement


DLT: 18.90ms

-0.09dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KR
(Kenny Wong)

Date: 7/8/03

Checked By: [Signature]
(Anthony Chan)

Date: 8/8/03

Test Result : Pass / Fail (NA)

DT: 0us

TS: 30ms

F: 49.860900MHz

Report No.: 03/2720
Model No.: 3215

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 1.50ms

-0.22dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 30ms

F: 49.860900MHz

Tested By: KA
(Kamuk Wong)
Date: 7/8/03

Checked By: Anthony Lee
(Anthony Lee)
Date: 8/8/03

Test Result : Pass / Fail (NA)

Report No.: 0312720
Model No.: 3215

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


DLT: 480us

-0.11dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kenneth Wang)
Date: 7/8/05

Checked By: [Signature]
(Anthony Chan)
Date: 8/8/05

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 49.860900MHz