



Date: 14 June, 2011

To: Timco Engineering Inc.
849 N.W. State Road 45
P.O. Box 370
Newberry, Florida 32669

To Timco Engineer,

We require to superseded the User Manual for FCC ID: QISG3511, which has been granted on April 14th, 2011.

We made following changes in the updated user manual:

1. P29, add Part15 FCC cautions;
2. P30, change Notify Body number from 0682 to 0700.

Please kindly list the updated user manual in FCC website!

Thank you for your attention to this matter.

Yours Sincerely,

A handwritten signature in black ink that reads "Wu Xuewen".

Xuewen.Wu
Certification Manager
Shenzhen Morlab Communications Technology Co., Ltd.