

INTERNAL Photographs

(Total 7 Pages including this Cover Page)

Supplement filename	Description
Photo-01	Heads of WD6DIPX220 (UMTS Band II, LTE band 2)
Photo-02	Rear of WD6DIPX220 (UMTS Band II, LTE band 2)
Photo-03	Heads of WD6DLPX240 (UMTS Band IV, LTE band 4)
Photo-04	Rear of WD6DLPX240 (UMTS Band IV, LTE band 4)
Photo-05	Heads of WD6EXRUIBA (pDock mother board (with three transmission ports))
Photo-06	Rear of WD6EXRUIBA (pDock mother board (with three transmission ports))
Photo-07	Heads of WD6EMRI (pDock mother board (with two transmission ports))
Photo-08	Rear of WD6EMRI (pDock mother board (with two transmission ports))




Photo-01 Heads of WD6DIPX220 (UMTS Band II, LTE band 2)




Photo-02 Rear of WD6DIPX220 (UMTS Band II, LTE band 2)




Photo-03 Heads of WD6DLPX240 (UMTS Band IV, LTE band 4)




Photo-04 Rear of WD6DLPX240 (UMTS Band IV, LTE band 4)




Photo-09 Heads of WD6EXRUIBA (pDock mother board (with three

transmission ports))




Photo-10 Rear of WD6EXRUIBA (pDock mother board (with three transmission ports))




Photo-11 Heads of WD6EMRI (pDock mother board (with two transmission ports))




Photo-12 Rear of WD6EMRI (pDock mother board (with two transmission ports))