





Band26_1.4MHz_QPSK_26797_1RB#0_3000~10000


Band26_1.4MHz_16QAM_26797_1RB#0_0.009~0.15_0.009~0.15




Band26_1.4MHz_16QAM_26797_1RB#0_0.15~3_0_0.15~30


Band26_1.4MHz_16QAM_26797_1RB#0_30~100_0_30~1000








Date: 24.DEC.2024 11:15:07




Date: 24.DEC.2024 11:15:16

Band26_1.4MHz_QPSK_26915_1RB#0_3000~10000

Band26_1.4MHz_16QAM_26915_1RB#0_0.009~0.15




Date: 24.DEC.2024 11:15:24




Date: 24.DEC.2024 11:15:33

Band26_1.4MHz_16QAM_26915_1RB#0_0.15~30


Band26_1.4MHz_16QAM_26915_1RB#0_30~100





Date: 24.DEC.2024 11:15:41





Date: 24.DEC.2024 11:15:50





Band26_1.4MHz_QPSK_27033_1RB#0_3000~10000

Band26_1.4MHz_16QAM_27033_1RB#0_0.009~0.15



Band26_1.4MHz_16QAM_27033_1RB#0_0.15~3

Band26_1.4MHz_16QAM_27033_1RB#0_30~100

