



LOSTnFOUND AG

Soodstrasse 55, Adliswil, Switzerland 8134

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Date: **March 28, 2013**

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: **FCC ID: RLS-STAVL1239**

To The Commission:

This Change of Identification request applies for a **new** FCC ID: **S47LNF1302** as established in 47CFR 2.933(b) for a currently approved device. This application by **LOSTnFOUND AG** will establish a new FCC ID under **S47** grantee code for purpose of marketing. The original grant to **RLS-STAVL1239** will remain in effect.

An authorization letter by **Systems & Technology Corp.** is attached.

Per 2.933(b)

1. The original identification is **RLS-STAVL1239**
2. The original grant date is **12/05/2012**
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

LOSTnFOUND® AG
Soodstrasse 55
CH-8134 Adliswil
SWITZERLAND

Daniel Thommen

LOSTnFOUND AG

Tel.: +41 44 500 40 95

Fax: +41 44 500 40 98

E-mail: daniel.thommen@lostnfound.com