

application
寄件人 : amanda.wu
吳鏗霽

收件人 : <mike.kuo@ccsemc.com>
副本抄送 :
主旨 : Re : LanReady Technologies Inc., FCC ID: SCD0031,
Assessment NO.: AN05T5112, Notice#1--待report

2005/09/07 04:24 PM

Dear Mike:

Please see our reply as below. Tks.

Best Regard

Amanda



"Compliance
Certification
Services"
<mike.kuo@ccsemc.co
m>

收件人 : amanda.wu@tw.ccsemc.com
副本抄送 :
主旨 : LanReady Technologies Inc., FCC ID: SCD0031, Assessment
NO.: AN05T5112, Notice#1

2005/09/05 07:23 PM

Hi Amanda,

Please address the following issues.

Question#1: The label is too vague to read, please provide clear one.

Ans:Please see the Label Smp & Lct.

Question#2: Please provide RF functional block and schematics.

Ans. Attached.

Question#3: FCC warning statement indicated in page 10 of user manual is movable by cursor, please correct.

Ans: The Page 10 of usermanual had been revised.

Question#4: According to the submitted block diagram, the EUT has POE function but test report didn't investigate it. Please provide the test data to demonstrate the compliance.

Ans: Sorry, in fact, the EUT doesn't have the "POE" function. So the blk dia had been revised.

Question#5: According to 15.247(b), if transmitting antenna gain is greater than 6 dBi, the conducted output power from the intentional radiator shall be reduced by the amount in dB. Please correct the limit of conducted output power.

Ans: The test report had been revised.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.