

	Report No: R3232 Issue No: 1	FCC ID: SEASENSOR30 IC: 8673A-SFNSOR30	
	Test No: T5014	Test Photos	Page: 1 of 3



dB Technology
----- (Cambridge Ltd.) -----
EMC Testing EMC Consultancy EMC Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

REPORT ON ELECTROMAGNETIC COMPATIBILITY TESTS

**Performed at:
TWENTY PENCE TEST SITE**

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Ubisense

Ubisensor 3.0

dated

19th June 2013

	Report No: R3232 Issue No: 1	FCC ID: SEASENSOR30 IC: 8673A-SFNSOR30	
Test No: T5014		Test Photos	Page: 2 of 3



Photograph 1 Conducted Emissions - Front



Photograph 2 Conducted Emissions - Back

	Report No: R3232 Issue No: 1	FCC ID: SEASENSOR30 IC: 8673A-SFNSOR30	
Test No: T5014		Test Photos	Page: 3 of 3



Photograph 3 Radiated Emissions - Front



Photograph 4 Radiated Emissions - Back