


Appendix D. SAR Test Setup Photos



USB Cable Plug-in for USB Configuration 1
(Horizontal Up, Test Separation 5 mm)




Direct Laptop Plug-in for USB Configuration 2
(Horizontal Down, Test Separation 5 mm)



USB Cable Plug-in for USB Configuration 3
(Vertical Back, Test Separation 5 mm)



Direct Laptop Plug-in USB Configuration 4
(Vertical Front, Test Separation 5 mm)



USB Cable Plug-in for USB Configuration 5
(Tip Mode, Test Separation 5 mm)