
27 June 2006

American TCB
6731 Whittier Avenue
McLean VA 22101

RE: Revolabs
Response to 26 June 2006 Comments

FCC ID: FCC ID T5V01EXEMIC / IC:6455A-01EVEMIC

Your comments 1. – 4 & 6 & 8 will need to be addressed by Joel and he is out of the office today. Please look for response from him on these comments tomorrow.

5. ATCB Comments: Please provide the manual for this device. Please include the highest SAR values and all appropriate Part 15 statements.

RESPONSE: I'm sorry, when I uploaded the exhibits I somehow missed several. The manual has now been uploaded.

7. ATCB Comments: Please provide the required test report. Please ensure that all aspects of 15 subpart D are fully addressed.

RESPONSE: Again I apologize, I have now uploaded the test reports and the test set-up photos for this product.

Please let us know if anything further is required and please copy me in addition to Joel and Jolene on all comments and responses regarding this submittal.

Susan L Rupp, Technical Writer
TÜV America Inc
Tel: 651 638 4585 / Fax: 651 638 0298
srupp@tuvam.com