

June 06, 2006

TRW Automotive U.S. LLC
d.b.a TRW Automotive Electronics
24175 Research Drive
Farmington Hills, MI 48335
Tel: 248.478.7210
Fax: 248.478.7241

& % \$ *

RE: Certification for TRW TPM '07 Highline Receiver
with Initiator

Receiver Model #: 95800-3M100

Initiator Model #: 95800-3E300

FCC ID: T7B-2R

Canada IC: 6484A-2R

FCC/IC IDENTIFIER AND MODEL NUMBER

Please see Figure 1 for the FCC/IC identifier location and the model number location.




Figure 1. Highline Receiver Model Number and FCC/IC Identifier

June 06, 2006

TRW Automotive U.S. LLC
d.b.a TRW Automotive Electronics
24175 Research Drive
Farmington Hills, MI 48335
Tel: 248.478.7210
Fax: 248.478.7241

& % \$ *

RE: Certification for TRW TPM '07 Highline Receiver
with Initiator

Receiver Model #: 95800-3M100

Initiator Model #: 95800-3E300

FCC ID: T7B-2R

Canada IC: 6484A-2R

Please see Figure 2 for the model number location.



Figure 2. Initiator Model Number

The model number for the Highline Receiver is:

95800-3M100

The model number for the Initiator is:

95800-3E300

The FCC ID for the Highline Receiver with Initiator is:

T7B-2R

The Canada IC ID for the Highline Receiver with Initiator is:

6484A-2R