



24 August 2021

Federal Communications Commission
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, Maryland 21046
United States of America

To Whom It May Concern:

RE: Description of change for FCC ID: UIPSQ450M140.

The Aprisa SR+ power supply and RF section has been updated for improved performance.

The RF circuits has had small changes to the transmitter and receiver. These include improvement transmitter and receiver synthesizer, the demodulators, etc.

Such changes have been tested with accompanied test reports to demonstrate they do not degrade the performance beyond that is allowed by the FCC.

For and on behalf of
4RF Limited
Sincerely,


Paul Young
Compliance Manager