



10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:42:14

10MHz_Low_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:42:34

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:42:54

10MHz_Middle_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:43:15

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:43:36

10MHz_High_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 17:43:56

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:44:58

15MHz_Low_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:45:18

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:45:39

15MHz_Middle_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:46:00

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:46:21

15MHz_High_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:46:43

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:47:53

20MHz_Low_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:48:13

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:48:33

20MHz_Middle_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:48:55

20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:49:17


20MHz_High_QPSK_100@0(30MHz~27.9GHz)



ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 17:49:38


LTE Band 66 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:40:14

1.4MHz_Low_QPSK_6@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:40:35

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:40:56

1.4MHz_Middle_QPSK_6@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:41:17

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:41:38

1.4MHz_High_QPSK_6@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:41:59

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:42:50

3MHz_Low_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:43:11

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:43:32

3MHz_Middle_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:43:53

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:44:13

3MHz_High_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22.MAY.2025 19:44:35

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:45:43

5MHz_Low_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:46:04

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:46:25

5MHz_Middle_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:46:46

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:47:07

5MHz_High_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:47:28

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:48:34

10MHz_Low_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:48:54

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:49:15

10MHz_Middle_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:49:36

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:49:58

10MHz_High_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:50:18

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:51:27

15MHz_Low_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:51:48

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:52:09

15MHz_Middle_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:52:30

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:52:52

15MHz_High_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA250319001 Tester: Jason Lu
Date: 22 MAY 2025 19:53:13

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:54:24

20MHz_Low_QPSK_100@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:54:44

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:55:06

20MHz_Middle_QPSK_100@0(30MHz~18.8GHz)




ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:55:27

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:55:48

20MHz_High_QPSK_100@0(30MHz~18.8GHz)



ProjectNo.:RKSA250319001 Tester:Jason Lu
Date: 22 MAY 2025 19:56:09

***** END *****