

Doro AB

Date: Oct. 19, 2020

Federal Communications Commission
Authorization and Evaluation Devision
7435 Oakland Mills Road
Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: WS5DFC0270
Original Grant Date: 8/8/2019
Applicant: Doro AB

Doro AB

Product Change Description

As the applicant of the below model, [Doro AB] declares that the product,

[DFC-0270]

[Doro AB]

HW: V01C(HW code: 4011/ 4021/5011/5021/5031/5041)

SW:DFC0270_VF292_N_S01A_V16_M200729_GCF

is the variant of the initial certified product,

[DFC-0270]

[Doro AB]

HW: V01(HW code: 4011, HW code: 4021)

SW: DFC0270_VF292_N_S01A_V04_0_M190710_SMP

SOFTWARE MODIFICATIONS:

Protocol Stack changes: NO

MMS/SUPL changes: NO

STK/USAT changes: NO

Browsing changes: NO

Other changes detailed: YES, SW compatible for Nanya memory

HARDWARE MODIFICATION:

Band changes: NO

Power Amplifier changes: NO

Antenna changes: NO

PCB Layout changes: No, only a monir modification on gerber to add a soldering pad

Components on PCB changes: YES, add a resistance

LCD changes: NO

Memory changes: YES, add Nanya memory

Speaker changes: NO

Camera changes: NO

Vibrator changes: NO

Bluetooth changes: NO

FM changes: NO

Other changes: NO

Doro AB

MECHANICAL MODIFICATIONS:

Use new metal front/back cover or keypad: NO

Mechanical shell changes: NO

Other changes detailed: NO


ACCESSORY MODIFICATIONS:

Battery changes: YES, add DBX-1350B new battery

AC Adaptor changes: NO

Earphone changes: NO

APPROVED BY:



Fredrik Bentsson. R&D Director Phones

Date: 2020-10-19

Company: Doro AB

Address: Jörgen Kocksgatan 1B, SE 211 20 Malmö, SWEDEN

Tel: +46 46 280 50 00