







Band2_5MHz_64QAM_18625_1RB#0




Band2_5MHz_64QAM_18625_1RB#24




Band2_5MHz_64QAM_18625_25RB#0




Band2_5MHz_64QAM_19175_1RB#0




Band2_5MHz_64QAM_19175_1RB#24




Band2_5MHz_64QAM_19175_25RB#0



Band2_10MHz_64QAM_18650_1RB#0




Band2_10MHz_64QAM_18650_1RB#49




11:11:47 29.12.2023

Band2_10MHz_64QAM_18650_50RB#0




11:11:59 29.12.2023

Band2_10MHz_64QAM_19150_1RB#0




11:12:08 29.12.2023

Band2_10MHz_64QAM_19150_1RB#49




11:12:16 29.12.2023


Band2_10MHz_64QAM_19150_50RB#0




Band2_15MHz_64QAM_18675_1RB#0




Band2_15MHz_64QAM_18675_1RB#74



Band2_15MHz_64QAM_18675_75RB#0




Band2_15MHz_64QAM_19125_1RB#0




11:20:48 29.12.2023

Band2_15MHz_64QAM_19125_1RB#74




11:20:57 29.12.2023

Band2_15MHz_64QAM_19125_75RB#0




11:28:55 29.12.2023

Band2_20MHz_64QAM_18700_1RB#0




11:29:05 29.12.2023

Band2_20MHz_64QAM_18700_1RB#99




11:29:13 29.12.2023

Band2_20MHz_64QAM_18700_100RB#0




11:29:25 29.12.2023

Band2_20MHz_64QAM_19100_1RB#0



11:29:34 29.12.2023

Band2_20MHz_64QAM_19100_1RB#99





11:29:43 29.12.2023

Band2_20MHz_64QAM_19100_100RB#0


Conducted Spurious Emission

Test Graphs







Band2_1.4MHz_QPSK_18607_1RB#0_3000~20000_3000~20000
0000




Band2_1.4MHz_16QAM_18607_1RB#0_0.009~0.15_0.009~0.15
15




Band2_1.4MHz_16QAM_18607_1RB#0_0.15~30_0.15~30




Band2_1.4MHz_16QAM_18607_1RB#0_30~1000_30~1000




Band2_1.4MHz_16QAM_18607_1RB#0_1000~3000_1000~3000




Band2_1.4MHz_16QAM_18607_1RB#0_3000~20000_3000~20000




Band2_1.4MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15




Band2_1.4MHz_QPSK_18900_1RB#0_0.15~30_0.15~30




Band2_1.4MHz_QPSK_18900_1RB#0_30~1000_30~1000




Band2_1.4MHz_QPSK_18900_1RB#0_1000~3000_1000~300
0



Band2_1.4MHz_QPSK_18900_1RB#0_3000~20000_3000~20000
0000




Band2_1.4MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15
15




18:16:29 12.11.2023

Band2_1.4MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




18:16:33 12.11.2023

Band2_1.4MHz_16QAM_18900_1RB#0_30~1000_30~1000




18:16:45 12.11.2023

Band2_1.4MHz_16QAM_18900_1RB#0_1000~3000_1000~3000




18:16:57 12.11.2023

Band2_1.4MHz_16QAM_18900_1RB#0_3000~20000_3000~20000




Band2_1.4MHz_QPSK_19193_1RB#0_0.009~0.15_0.009~0.


15



Band2_1.4MHz_QPSK_19193_1RB#0_0.15~30_0.15~30




Band2_1.4MHz_QPSK_19193_1RB#0_30~1000_30~1000




Band2_1.4MHz_QPSK_19193_1RB#0_1000~3000_1000~300


0




Band2_1.4MHz_QPSK_19193_1RB#0_3000~20000_3000~20000




Band2_1.4MHz_16QAM_19193_1RB#0_0.009~0.15_0.009~0.15




Band2_1.4MHz_16QAM_19193_1RB#0_0.15~30_0.15~30




Band2_1.4MHz_16QAM_19193_1RB#0_30~1000_30~1000




Band2_1.4MHz_16QAM_19193_1RB#0_1000~3000_1000~3000




Band2_1.4MHz_16QAM_19193_1RB#0_3000~20000_3000~20000



Band2_3MHz_QPSK_18615_1RB#0_0.009~0.15_0.009~0.15




Band2_3MHz_QPSK_18615_1RB#0_0.15~30_0.15~30




18:19:46 12.11.2023

Band2_3MHz_QPSK_18615_1RB#0_30~1000_30~1000




18:19:57 12.11.2023

Band2_3MHz_QPSK_18615_1RB#0_1000~3000_1000~3000




18:20:09 12.11.2023

Band2_3MHz_QPSK_18615_1RB#0_3000~20000_3000~2000
00




18:20:25 12.11.2023

Band2_3MHz_16QAM_18615_1RB#0_30~1000_30~1000




Band2_3MHz_16QAM_18615_1RB#0_1000~3000_1000~3000

0




Band2_3MHz_QPSK_18900_1RB#0_3000~20000_3000~2000

0




Band2_3MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.1

5




Band2_3MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




18:21:46 12.11.2023

Band2_3MHz_16QAM_18900_1RB#0_30~1000_30~1000




18:21:57 12.11.2023

Band2_3MHz_16QAM_18900_1RB#0_1000~3000_1000~3000




18:22:09 12.11.2023

Band2_3MHz_16QAM_18900_1RB#0_3000~20000_3000~20000




18:22:33 12.11.2023


Band2_3MHz_QPSK_19185_1RB#0_0.009~0.15_0.009~0.15




Band2_3MHz_QPSK_19185_1RB#0_0.15~30_0.15~30



Band2_3MHz_QPSK_19185_1RB#0_30~1000_30~1000




Band2_3MHz_QPSK_19185_1RB#0_1000~3000_1000~3000




Band2_3MHz_QPSK_19185_1RB#0_3000~20000_3000~2000

0




Band2_3MHz_16QAM_19185_1RB#0_1000~3000_1000~300

0




Band2_3MHz_16QAM_19185_1RB#0_3000~20000_3000~200


00




Band2_5MHz_QPSK_18625_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_QPSK_18625_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_18625_1RB#0_30~1000_30~1000



Band2_5MHz_QPSK_18625_1RB#0_1000~3000_1000~3000



Band2_5MHz_QPSK_18625_1RB#0_3000~20000_3000~2000
00



Band2_5MHz_16QAM_18625_1RB#0_0.009~0.15_0.009~0.15