

Andrew Wireless Systems GmbH  
Industriering 10  
86675 Buchdorf  
Germany





















Nemko Canada Inc  
303 River Road  
Ottawa  
K1V 1H2  
Canada

ATTN.: Reviewing Engineer

FCC ID: XS5-UAP217192537

## Model differences - Annex

Photographic comparison to show the hardware differences among the variants under this filing:

Views	UAP 2 17E/19/25T/37T C-PE	UAP 2 17E/19/25T/37T F-DC	UAP 2 25T/37T C-PE	UAP 2 25T/37T F-DC
Antennas side				
Radio Modules installed				
Base Band Card (all)				
Data & Power Entry	 	 	 	 

Signed:



Printed name: Jiri Cecka  
Title: Quality Manager  
Date: 10/9/2023