

Watchdata Technologies Pte Ltd Web Site: www. watchdata.com Email: webmaster@watchdata.com	84 Genting Lane, #02-01 Cityneon Design Centre, Si Singapore Tel: +65 6779 3050 Fax: +65 6779 2460
--	--

### Request for Class II Permissive Change

FCC ID: Y97WATCHW1981

Date: August 24, 2012

To: Federal Communication Commission

Please be notified that we, the undersigned, Watchdata Technologies Pte Ltd Declare that the reason for this Class II permissive change are as below:


- 1 Reduce several resistors and capacitors from the PCB layout.
- 2 Reduce the magnetic ring from the USB cable.

Please refer to below form for detailed information:

Item	Key Component Deviation		Remarks
	Original design	Current design	
several resistors and capacitors on the PCB layout	With these components	Without these components	Design optimization
Magnetic ring on the USB cable	With magnetic ring	Without magnetic ring	Design optimization

Thanks!

Sincerely,



Geng Jianhua / Product Engineer  
 Watchdata Technologies Pte Ltd  
 Tel: +65 6779 3050  
 Fax: +65 6779 2460  
 Email: chunhui.dong@watchdata.com