Appendix D. SAR Test Setup Photos

Head Exposure Condition (Right Arm)



Report No.: FA231534-01

Right inner surface at 0 mm

Right outer surface at 0 mm



Right Back surface at 0 mm



Right Front surface at 0 mm

TEL: 886-3-327-3456 Page: D1 of D3
FAX: 886-3-328-4978 Issued Date: Oct. 04, 2022

Template version: 211220

Head Exposure Condition (Left Arm)





Report No.: FA231534-01

Left inner surface at 0 mm

Left outer surface at 0 mm








Left Front surface at 0 mm

TEL: 886-3-327-3456 Page: D2 of D3
FAX: 886-3-328-4978 Issued Date: Oct. 04, 2022

Template version: 211220

Appendix D. Antenna Location



Report No.: FA231534-01

TEL: 886-3-327-3456 Page: D3 of D3
FAX: 886-3-328-4978 Issued Date: Oct. 04, 2022

Template version: 211220