


**Apparatus Internal Photographs**  
**Project C4113**  
**Digital Barriers**  
**Tested at Eurofins York**  
**Unit 5, speedwell road Castleford, WF10 5PY**




Apparatus disassembled



Apparatus disassembled, battery removed

C4113

23/07/18



Circuit board

C4113

23/07/18



Component Side

C4113

23/07/18



Underside

C4113

23/07/18



Battery