



Test Set Up Photographs
Project C4113
Digital Barriers
Tested at Eurofins York
Unit 5, speedwell road Castleford, WF10 5PY




Radiated Emissions 30MHz to 1GHz




Radiated Emissions 30MHz to 1GHz




Radiated Emissions 1GHz to 10GHz Exploratory Measurements




Radiated emissions 1GHz to 10GHz



Antenna Port conducted Test (6dB Bandwidth)



Antenna Port conducted Test (Spurious Emissions)



Antenna Port conducted Test (Spectral Density)