


	Report No: <b>R3301</b> Issue No: <b>2</b>	FCC ID:2ABPQ-ZHC	
Test No: <b>T5172</b>		<b>Test Photos</b>	Page: <b>1 of 4</b>



**dB Technology**  
----- (Cambridge Ltd.) -----  
EMC Testing      EMC Consultancy      EMC Training

23, Headington Drive,  
Cambridge.  
CB1 9HE  
Tel : 01954 251974 (test site)  
or : 01223 241140 (accounts)  
Fax : 01954 251907  
web : [www.dbtechnology.co.uk](http://www.dbtechnology.co.uk)  
email: [mail@dbtechnology.co.uk](mailto:mail@dbtechnology.co.uk)

## REPORT ON ELECTROMAGNETIC COMPATIBILITY TESTS

**Performed at:  
TWENTY PENCE TEST SITE**

**Twenty Pence Road,  
Cottenham,  
Cambridge  
U.K.  
CB24 8PS**

**on**

**ZHC Systems Ltd**

**ScanMonkey**

**dated**

**28th January 2014**

### Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	28/01/14		Initial release		
2	05/02/14	All	Manufacturer name changed	DS	DB

Based on report template:  
v090319

*This report shall not be reproduced except in full, without the written approval of:  
dB Technology (Cambridge) Ltd.*

	Report No: <b>R3301</b> Issue No: <b>2</b>	FCC ID:2ABPQ-ZHC	
	Test No: <b>T5172</b>	<b>Test Photos</b>	Page: <b>2 of 4</b>


## Contents

<i>Photograph 1</i> <i>Conducted Emissions : Front</i> .....	3
<i>Photograph 2</i> <i>Conducted Emissions : Back</i> .....	3
<i>Photograph 3</i> <i>Radiated Emissions : Front</i> .....	4
<i>Photograph 4</i> <i>Radiated Emissions : Back</i> .....	4

	Report No: <b>R3301</b> Issue No: <b>2</b>	FCC ID:2ABPQ-ZHC	
Test No: <b>T5172</b>		<b>Test Photos</b>	Page: <b>3 of 4</b>




**Photograph 1 Conducted Emissions : Front**



**Photograph 2 Conducted Emissions : Back**

	Report No: <b>R3301</b> Issue No: <b>2</b>	FCC ID:2ABPQ-ZHC	
Test No: <b>T5172</b>		<b>Test Photos</b>	Page: <b>4 of 4</b>



**Photograph 3 Radiated Emissions : Front**



**Photograph 4 Radiated Emissions : Back**