

Appendix 2

Photodocumentation


Division:
Industry & Energy

Description: Battery compartment opened

Test report reference:
2024-AT-TC-EE-ET-EX-0-
000005-FG-066

Page: 3 of 10

Date: 07.01.2025



Appendix 2 Photodocumentation


Division:
Industry & Energy

Description: Case opened

Test report reference:
2024-AT-TC-EE-ET-EX-0-
000005-FG-066

Page: 4 of 10

Date: 07.01.2025



Appendix 2

Photodocumentation


Division:
Industry & Energy

Description: Internal view #1

Test report reference:
2024-AT-TC-EE-ET-EX-0-
000005-FG-066

Page: 5 of 10

Date: 07.01.2025



Appendix 2 Photodocumentation


Division:
Industry & Energy

Description: Internal view #2

Test report reference:
2024-AT-TC-EE-ET-EX-0-
000005-FG-066

Page: 6 of 10

Date: 07.01.2025



Appendix 2 Photodocumentation

Description: Antenna detail

Division:
Industry & Energy

Test report reference:
2024-AT-TC-EE-ET-EX-0-
000005-FG-066

Page: 7 of 10

Date: 07.01.2025

