






















Conducted RF Spurious Emission


Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	b	2412	Ant1	-45.67	-20	Pass
NVNT	b	2437	Ant1	-47.41	-20	Pass
NVNT	b	2462	Ant1	-46.94	-20	Pass
NVNT	g	2412	Ant1	-40.2	-20	Pass
NVNT	g	2437	Ant1	-40.97	-20	Pass
NVNT	g	2462	Ant1	-41.48	-20	Pass
NVNT	n20	2412	Ant1	-38.73	-20	Pass
NVNT	n20	2437	Ant1	-39.72	-20	Pass
NVNT	n20	2462	Ant1	-40.01	-20	Pass
NVNT	n40	2422	Ant1	-38.22	-20	Pass
NVNT	n40	2437	Ant1	-37.72	-20	Pass
NVNT	n40	2452	Ant1	-37.98	-20	Pass





















APPENDIX II - MEASUREMENT PHOTOS

Note: Please see the attached RF_Test Setup photos for FCC ID & IC.

※※※※※END OF THE REPORT※※※※※