




Report No.: EED32O80125302

## **8 PHOTOGRAPHS OF TEST SETUP**

Test model No.: G1



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)





Report No.: EED32O80125302



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 









