





## 7 PHOTOGRAPHS OF TEST SETUP

Test model No.: iSmartTool 601Max



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)






Report No.: EED32N80831501



**Conducted Emissions Test Setup** 



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.









