

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical: X-axis)

Above 1 GHz (Horizontal: X-axis/ Vertical: Y-axis)

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report