



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**


Front



Rear (below 1 GHz)



Rear (above 1 GHz)



### Pre-check of Worst Case Position

Module  
X-axis



Antenna  
X-axis



Y-axis




Y-axis



Z-axis



Z-axis



**End of Report**