

APPENDIX 3: Photographs of test setup

Conducted Emission

Front



Rear



Radiated Emission


Front



Rear (below 1GHz)



Rear (above 1GHz)






UL Kashima, Inc.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81-478-82-0963

Facsimile: +81-478-82-3373

Pre-check of the worst position**X-axis****Y-axis****Z-axis****End of Report**

UL Kashima, Inc.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81-478-82-0963

Facsimile: +81-478-82-3373