



APPENDIX 3: Photographs of test setup


Radiated Spurious Emission



Front



Rear(Below 1 GHz)



Rear(Above 1 GHz)

Antenna Terminal Conducted Tests



Photo 1



Photo 2

End of Report