

TEST SETUP PHOTOS


SENSE BICON HORIZ UUT HORIZ



SENSE BICON HORIZ UUT VERT



SENSE BICON HORIZ UUT OBLQ



SENSE BICON VERT UUT HORIZ



SENSE BICON VERT UUT VERT



SENSE BICON VERT UUT OBLQ



SENSE LOOP 0° UUT HORIZ




SENSE LOOP 0° UUT VERT



SENSE LOOP 0° UUT OBLQ



SENSE LOOP 0-90° UUT HORIZ



SENSE LOOP 0-90° UUT VERT



SENSE LOOP 0-90° UUT OBLQ



SENSE LOOP 90° UUT HORIZ



SENSE LOOP 90° UUT VERT



SENSE LOOP 90° UUT OBLQ



TEST SETUP PHOTOS (CONT.)

PICTURE OF THE OATS AT
2 CORPORATE CENTER DRIVE
MELVILLE, NY 11747



TEST SETUP PICTURES (CONT.)
CLASS B CONDUCTED EMISSIONS

