

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission



Photo 1




Photo 2

Worst Case Position

Test Range		Horizontal	Vertical
Below 1 GHz	Cockpit Control Unit	X-axis	X-axis
	Antenna	X-axis	X-axis
Above 1 GHz	Cockpit Control Unit	X-axis	X-axis
	Antenna	Y-axis	X-axis

**(Cockpit Control Unit)
X-axis**



Y-axis




Z-axis




**(Antenna)
X-axis**



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report