

Report No.: 99007211

Tested By: Hong, Report No.: 99007211

Scan Settings (1 Range)


----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	2K	20ms	AUTO	LN OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078

Final Measurement: 0 QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A

Report No.: 99007211

Tested By: Hong, Report No.: 99007211

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

16.00000	26.6	48.0
----------	------	------

* limit exceeded

Ctrl. No.: N/A