



# TX Module Schematics





C4 removed, L3 was 3N6, L4 was 2N7, ANT1 was 2450AT18B100E

