

## 7. Photographs of the Test Set-Up


Photograph 1: Set-up for Spurious Emissions (Front View)




Photograph 2: Set-up for Spurious Emissions (Back View 1)



**Photograph 3: Set-up for Spurious Emissions (Back View 2)**



**Photograph 4: Set-up for Conducted testing**



**Prüfbericht - Nr.:** 10039980 001  
Test Report No.

Seite 39 von 40  
Page 39 of 40

**Photograph 5: Set-up for Mains Conducted Emissions (Front View)**



**Photograph 6: Set-up for Mains Conducted Emissions (Back View)**

