

5 Annex B Photographs of Test site

Photo 1 (Radiated Emissions):



Photo 2 (Radiated Emissions):



Photo 3 (Radiated Emissions):




Photo 4 (Radiated Emissions):




Photo 5 (Radiated Emissions):




Photo 6 (Conducted Emissions):



6 Annex C: External Photographs of the Equipment

Photo No.: 1



Photo No.: 2



Photo No.: 3



Photo No.: 4



Photo No.: 5



Photo No.: 6



Photo No.: 7



Photo No.:8



Photo No.: 9



7 Annex D: Internal Photographs of the Equipment

Photo No.: 1



Photo No.: 2




Photo No.: 3




Photo No.: 4




Photo No.: 5




Photo No.: 6




Photo No.: 7



Photo No.: 8

