

Prüfbericht - Nr.: 16002953 001
Test Report No.:

Seite 15 von 17
Page 15 of 17

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission on AC Mains



Photograph 2: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.: 16002953 001

Test Report No.:

Seite 16 von 17

Page 16 of 17

Photograph 3: Set-up for Radiation Measurement Above 1GHz

