


COTATION - DETOURAGE


P01x115-C



CUIVRE 1

1


P01x115-C



CUIVRE 2

4

P01x115-C



PLAN EQUIPEMENT 1


U6 / C74 Double implant.

1

P01x115-C

D2 / C78 Double implant.

Q4 / C73 Double implant.




C49 / R6 Double implant.

C3

PLAN EQUIPEMENT 2

4

P01x115-C




SOM10

SIM00

COUCHE INTERNE 2

	2		
--	---	--	--


P01x115-C



COUCHE INTERNE 3


		3	
--	--	---	--

P01x115-C



PLAN DE PERCAGES


P01x115-C

[illegible]

PLAN EQUIPEMENT 1

W_K_915

1 P01x115-C



Double implant.

C33 R22 C43 R19 C40

PLAN EQUIPEME 2

W_K_915

4
P01x115-C

