

Test# 186-05 Opticon Radiated Test Setup Front



A small PVC pipe cut off was used to hold the EUT in position for testing.

Test# 186-05 Opticon Radiated Test Setup Rear



The metal sheet in the background is the door to the OATS, it was closed during testing.