


Test setup photos of PC 88903

1. Conducted Emission Test setup




Front View




Rear View

2. Radiated Emission Test

Blow 1GHz




Front View




Rear View

Above 1GHz



Front View



Rear View