



Test setup photos

1. Part 22/24 radiated spurious emission below 3GHz




2. Part22/24 radiated spurious emission above 3 GHz





Ancillary Equipment 1



Ancillary Equipment 2