




Photograph B-1: Radiated Emissions Test – Washington Laboratories OATS – Front View



Photograph B-2: Radiated Emissions Test – Washington Laboratories OATS – Rear View




*Photograph B-3: Radiated Emissions Test – CURRENT Technologies Field Research and Test Area, Pole P4- Wide View*



*Photograph B-4: Radiated Emissions Test – CURRENT Technologies Field Research and Test Area, Pole P4- Close View*



*Photograph B-5: Radiated Emissions Test – CURRENT Technologies Rockville Test Area, Macon Road - Wide View*



*Photograph B-6: Radiated Emissions Test – CURRENT Technologies Rockville Test Area, Macon Road – Close View*



*Photograph B-7: Radiated Emissions Test – CURRENT Technologies Rockville Test Area, Old Drovers Way - Wide View*



*Photograph B-8: Radiated Emissions Test – CURRENT Technologies Rockville Test Area, Old Drovers Way– Close View*